

# IPReceiver and DC-09 Receiver for Manitou

May 2025





### Contents

Overview	2
Setup	2
Service and File Setup	2
IPReceiver appsettings.json Setup	4
Supervisor Workstation MSM Configuration Setup	5
SIA2 Receiver Setup	8
Verify Connectivity	10
General Information	11

## BCLD GROUP

#### **Overview**

We updated the IPReceiver to handle DC-09 signalling. These changes require the installation of the IPReceiver; an update to Receiver Types; and new Event Mapping for SIA 2000.

#### Setup

These changes are included in version 2.1 patch 45. Install patch 45 and run the database migrations before continuing with this setup.

#### **Service and File Setup**

Verify if there is an existing IPReceiver service installed. This can be done by opening the Service Manager and looking for the Bold IP Receiver service.

	G Bold Distributer	Manitou Dis	Running	Automatic	Local System
	Bold Distributer Client	Manitou Dis	Running	Automatic	Local System
-	Bold Integration Gateway			Manual	Local System
	Bold IP Receiver			Manual	Local System
	Sold License Manager		Running	Automatic	Local System
	Bold Local Utility Service	Manitou Lo	Running	Automatic	Local System
	Bold Location Server			Manual	Local System
	🔅 Bold Logger	Manitou Lo	Running	Manual	Local System
	端 Bold Marshaller	Manitou M	Running	Manual	Local System
	Pald Madie Catanana	DeldMadia	Duraning	Manual	I a sel Custom

If the service is preexisting, it is likely set to run from C:\Program Files (x86)\Bold Technologies\Manitou.

The old service must be removed before the new IPReceiver can be installed.

To remove the old service:

- 1. Open a Command Prompt as Administrator.
- 2. Type in CD then paste the path C:\Program Files (x86)\Bold Technologies\Manitou and press enter.
- 3. Type 'ipreceiver.exe -remove' (without the quotes) and press enter.
- 4. Refresh the Service Manager and verify that the service is no longer listed.

In the Manitou folder create a new folder named IPReceiver.

Copy the new IPReceiver files into the newly created folder. The files are in Package 10. On initial setup the files will need to be manually copied. Once the files are in Manitou\IPReceiver the DistCommander

## BCLD G R O U P

can be used to push new files. However, because the appsetting.json file has configuration information, the DistCommander will not push a new appsetting.json file so it does not overwrite configured data. It is best practice to back up previous files before upgrading.

To add the new service:

- 1. Open a Command Prompt as Administrator.
- 2. Type in CD; then paste the path C:\Program Files (x86)\Bold Technologies\Manitou\IPReceiver; and press enter.
- 3. Type 'ipreceiver.exe -install' (without the quotes) and press enter.
- 4. Refresh in the Service Manager and verify that the service shows.
- 5. Click on the properties of the service and verify that the **Service name** correctly shows as BOLD\_IPRECEIVER and that the **Path to the executable** shows correctly.

Bold IP	Receiver Properties (Local Computer)
General Log On	Recovery Dependencies
Service name:	BOLD_IPRECEIVER
Display name:	Bold IP Receiver
Description:	∧ ▼
Path to executable "C:\Program Files	e: (x86)\Bold Technologies\Manitou\IPReceiver\IpReceive
Startup type:	Manual V
Service status:	Stopped
Start	Stop Pause Resume
You can specify the from here.	he start parameters that apply when you start the service
Start parameters:	
	OK Cancel Apply



#### **IPReceiver appsettings.json Setup**

Before adding the service to the MSM configuration, update the appsettings.json file in the IPReceiver folder.

Using the appsettings.json for configuration will give the ability to add more receiver types later, but for now it is just defaulted with the DC-09 configuration.

Open the appsettings.json file in notepad.

```
K
  "Logging": {
    "LogLevel": {
      "Default": "Information",
      "Microsoft": "Warning",
      "Microsoft.Hosting.Lifetime": "Information"
   }
  },
  "Plugins": {
    "AlarmProvider": "ManitouAlarmProvider.dll",
    "ReceiverProviders": [ "Dc09ReceiverProvider.dll" ],
    "LoggingProvider": "ManitouLoggerProvider.dll"
 },
  // Use this section if you're using the DC-09 receiver driver
  "DC-09": {
    "Routes": [
      {
       // If specified, will expect incoming messages on this route to be encrypted with this key.
       // Must be a 128, 192, or 256-bit hex string (32, 48, or 64 characters)
       // NOTE: AS THIS IS A KNOWN DEFAULT KEY, DO NOT USE THIS KEY. BUILD A NEW KEY.
       "EncryptionKey": "12345678901234567890123456789012",
        // This is the UDP port upon which to listen for incoming signals for this route.
        "UdpListenPort": 6002,
        // Number of seconds between NULL line supervision signals. Set to 0 to disable supervision.
       "SupervisionSeconds": 10,
        // Number of seconds to wait for a response to a supervision message before attempting a retry.
       "ResponseTimeoutSeconds": 5,
        // Number of retries to pursue before giving up on sending the signal.
        "FailRetryCount": 3,
        // If the panel responds DUH, should we retry the signal?
        "RetryDuh": false
      }
   ]
 },
  // Use this section if you're using the Manitou alarm driver
  "Manitou": {
    "FepPort": 5555
 }
}
```



NOTE: The default encryption key is not a valid encryption key. The encryption key would likely come from the Dealer who already has it programmed at the panel level.

The defaulted UdpListenPort is 6002. This will need to be updated based on customer needs.

The defaulted FEPPort is 5555. The is the port that you will assign to the SIA2 receiver later in the Supervisor Workstation FEP > Receivers setup. This port number will also need to be updated based on customer needs.

Save the changes to the appsettings.json file.

#### **Supervisor Workstation MSM Configuration Setup**



Open a Supervisor Workstation and navigate to Maintenance > Setup > Configuration.

Click Edit.



Click Applications under the server you are adding the service to and click the Add button. In the **Application Type** drop down, select the **App Type** 34 IP Receiver and click OK.

	Add	Application	
Application Type:	1	•	
Description:	App Type	Description	^
	34	IP Receiver	cel
	35	QuickBooks Invoice Generator Web Gateway	
	37	WIN-PAK Gateway	
	38	Sedona Invoice Generator Import Utility	
	40	XML Gateway	$\sim$

Select the machine where you would like the logger data to output to. The Broker connection and Logger is defaulted to localhost.

Save the changes.



Open the MSM or refresh the MSM and verify that the IPReceiver shows and is red.



Open the Log Viewer and uncheck everything except for the Monitor and the IPReceiver.

In the MSM, right click and select Start to start the IPReceiver service.

The light in the MSM should go green and the logger data look like this:

<u>8</u>	Manitou Log Viewer	= 0 X	O QAManitouA Primary     O A Soutem
The Edt Options Help           Log Level [Debug (4)]         ■         Image: Control (1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1	Manitou Log Viewer  *Starting BOLD_IPRICEIVER on QAL64CUST: AppType [34] (Args): QAL64CUST To Loading a plugin assembly from: Ci-Virogram Tiles (#66]\Bold Technologie4VManitou\IPs To Loading a plugin assembly from: Ci-Virogram Tiles (#66)\Bold Technologie4VManitou\IPs Manitou Provider using pommand Il\Forgram Tiles (#66)\Bold Technologie4VManitou\IPs TM Manitou Altern Provider Starting. TF Checking DC-09 optiguration TF DC-09 Receiver Starting. TF DC-09 Receiver Starting. TF DC-09 route manager: starting DC-09 UDP listener for port 6002	Loger O Brief O Serier O Serie	Image: Second State Second State       Image: Second State <td< th=""></td<>
4/2/2025 12123:15 0000 00010 3 0600 IP Beens 4/2/2025 12123:15 0000 00003 3 0600 IP Beens 4/2/2025 12123:15 0000 00005 3 06000 IP Beens 4/2/2025 12123:15 0000 00005 3 0600 IP Beens	rr DC-09 listener Fasting es per 6002. r Application started, Nosting evidence: Production; Content root path: Gi\Program Waiting for a DC-09 signal on pert 6002	Adschart     Adschart     Publicher     Publicher     Publicher     Publicher     Publicher     Publicher     Overstuck     Overstuck     Overstuck     Overstuck     Overstuck     Overstuck     Publicher     Overstuck     Publicher     Overstuck     Publicher     Overstuck	Al Evert Prive Transal     Constraint Serve Transal     Videnbog     Orado Dacida     Videnbog     Orado Dacida     Orado Dacida     Orado Dacida     Orado Senda (Insual)     Orado Senda (In



#### **SIA2 Receiver Setup**

In the Supervisor Workstation navigate to Maintenance > Setup > Receiver Types.

The Database Migrations from patch 45 include two new Receiver Types: one for SIA1 and one for SIA2. The default options for both are VER=1 or VER=2 respectively.

Other options are as follows:

Option	Default	Description
VER	1	Version. Indicates the receiver type (i.e., 1, 2).
HB	1	Heartbeat. Indicates whether to expect receiver heartbeat $(0 = No)$ .
TS	1	Timestamp. Indicates whether to validate message timestamp.
USECRC	1	CRC. Indicates whether to validate message $crc$ (0 = No).
CHKSEQ	0	Validate message sequence number $(0 = No)$ .
OPTSK	1	Silent Knight. Indicates the receiver type (i.e., 0, 1, 2)

For the DC-09 integration you will be using the SIA2 Receiver. The receiver setup will look something like this depending on the Options based on the customer needs.

Rece	iver Types				-
	Receiver Code:	SIA2			
	Name:	SIA Type 2			
	Attributes:				
	Driver:	SIA	Ŧ	SIA Type 1 OR 2	
	Options:	VER=2,DEBUG=1	-		

Save any changes that were made.

In the Supervisor Workstation navigate to Maintenance > Setup > Receivers and click Edit.

Highlight the FEP under which the new receiver will be added and click Add.



In the **Receiver type** select SIA2, add a **Description**, and then click OK.

	Add Receiver
Receiver type:	SIA2
Description:	SIA2 DC-09
Starting Number:	70 ÷
Number to Add:	1 +
	OK Cancel

In the **Port Type** dropdown, select *TCP/IP* (Out).

Update the **Host IP** as localhost or the IP of where the FEP is running.

The **Port Number** must match what is in the appsettings.json for the FEPReceiver Port (FepPort).

Receive	ris	
	Receiver Number:	69
	Receiver Type:	SIA2
	Description:	SIA2 1
	Port Type:	TCP/IP (Out)
	Host IP:	127.0.0.1
	Port Number:	5555
	Host IP (Secondary):	
	Port Number (Secondary):	
	Soft Command Receiver Code:	
		☐ Disabled
Defaults	·	
	Default Receiver Line Prefix:	RL 00
	Default Monitoring Group:	Monitoring Group 0
Default	Designation for Unknown Signals	
	Designation for Onknown Signals.	
105	Receiver Line Prefix:	
	Transmitter ID;	Default Beceiver testing
Linked F	feceiver:	
	FEP Number:	<b>_</b>
	Receiver Number:	



Select the **Default Receiver Line Prefix** (based on the customer needs) and the **Default Monitoring Group**.

Complete the fields in the **Default Designation for Unknown Signals** section. Add any Receiver Line Prefixes based on the customer needs.

Save the changes.

#### **Verify Connectivity**

Open the Log Viewer with only the FEP and IPReceiver checked.

Open the FEP Commander.

Right click on the IPReceiver in the MSM and start the IPReceiver service.

Watch the Log Viewer for any errors. The logger output should look something like this:

FEP	*FEP Call: Load Driver
FEP	*FEP Driver Thread Starting - SIA
FEP	*Loading FEP Driver [SIA.fep].
FEP	*SIA2 (RecNo 69): startup parameter VER [2]
FEP	*SIA driver starting in Type 2 mode (DC-07)
FEP	*StartDriver entry point in DLL
FEP	*SIA2 Receiver 69 [FEP 1] - Connection Established
FEP	*Driver Thread Loaded - SIA2
FEP	* SIA2: 1 <sub>1</sub> 69 <sub>1</sub> 0 DNIS <sub>1</sub> 03042025 <sub>1</sub> 155854 <sub>1</sub> SIA2 <sub>1</sub> 00000000 0000000000000000000000000000
FEP	*Connection With Receiver Established: 69 (SIA2)
FEP	*FEP sent another 0001 signals - invited 2000 (00000011)



In the FEP Commander verify that the driver for SIA2 shows as Started and that the status is Up.

	FEP Commander - localhost									
File	Edit View Status	FEP Core Dr	ivers Signals	Help						
BOX	Q 😪 🐚 🎊 🛝		9							
<u> </u>			•							
		1								
	Thread Type	Thread Status	Driver Name	Driver Status	Rec	No   Signals Sent	Last Send			
01	Listen	Started								
02	Standby	Started								
03	Log	Started								
04	Delivery	Started				0	0			
06	Driver	Started	ADEMCOY	Comms Failure	1	0				
07	Driver	Started	CHECKVID	TCP Listen	2	0				
09	Driver	Started	BOLDXML	TCP Listen	3	0				
08	Driver	Started	MG	Comms Failure	20	0				
08	Driver	Started	BOLDMG	Comms Failure	21	0				
00	Driver	Started	DMPFP	Comms Failure	34	0				
00	Driver	Started	RSIFRONT	TCP Listen	35	0				
10	Driver	Started	BOLD XML	Comms Failure	36	0				
0.4	Driver	Started	MLR2/SYS	TCP Listen	37	0				
OE	Driver	Started	MLR2/SYS	TCP Listen	39	N 0				
12	Driver	Started	SUREVIEW	TCP Listen	47	rs 0				
11	Driver	Started	OE	TCP Listen	61	0				
13	Driver	Started	MLR2	TCP Listen	65	0				
14	Driver	Started	BOI DXMI	TCP Listen	68	Û				
OF	Driver	Started	SIA2	Up	69	1	04/03 15:07:42			
105	Control	Started								
1										
Read	/						Connected //.			

#### **General Information**

#### Note: Currently IPReceiver only uses UDP, not TCP.

The maximum Event Code length that is accepted is two characters. If an event code is longer than two characters it will still process the signal, however it will only use the first two characters.



If Error shows as the status of the Driver in the FEPCommander:

				FEP Cor	nmander - I	ocalhost		_ <b>D</b> X
File	e Edit	View Status	FEP Core [	Drivers Signa	ls Help			
ିତ୍ୱ	ୁ ବ୍ଳ	s 🐚 🖉 🖄	i 🕞 😡 💿	2				
	• •			1 - 1				
Пп		Thread Turne	Thread Stat	Driver Name	Driver Statue	Rec No.	Signals Sent	Last Sand
	1	Listen	Started	Differritanic	Driver Status	neeno	- Signals Serk	Edist Serie
	12	Standbu	Started					
	12	Log	Started					
	14	Deliveru	Started				0	0
	6	Driver	Started	ADEMCOY	Comms Fail	1	ñ	ů
	5	Driver	Started	CHECKVID	TCP Listen	2	ñ	
l l i	9	Driver	Started	BOLDXML	TCP Listen	3	ŏ	
	18	Driver	Started	MG	Up	20	1	04/02 19:09:02
	)7	Driver	Started	BOLDMG	Úp	21	1	04/02 19:09:06
	A	Driver	Started	DMPFP	Comms Fail	34	Ó	
	B	Driver	Started	RSIFRONT	TCP Listen	35	0	
	)C	Driver	Started	BOLD XML	Comms Fail	36	0	
	E	Driver	Started	MLR2/SYS	TCP Listen	37	0	
1	0	Driver	Started	MLR2/SYS	TCP Listen	39	0	
	D	Driver	Started	SUREVIEW	TCP Listen	47	0	
1	3	Driver	Started	OE	TCP Listen	61	0	
	)F	Driver	Started	MLR2	TCP Listen	65	0	
1	2	Driver _	Started	ROLDXMI	TCP Listen	68	0	
1	5	Driver	Error	SIA2	Config Probl	69	0	
1	4	Control	Statted					
Rea	dy					[		Connected //

The possible issues are that the Port is not set correctly to TCP/IP Out or that the port is in use by something else.